IDEA-0931 Copy of 8

1 November 1962

	MEMORANDUM	FOR : Assistant Di	rector, Office of S	Special Activities	
	SUBJECT	: Removal of A	rticle 342	25X1A	i
25X1A	direct question,		dsted to our reme	ctober, in response to a oving Article 342 from h by Lockheed of the	
25X1A	necessary	He said that D	r. Charyk had cal	lled General Taylor	İ
	•	eting 31 October and t			: !
	Z. Dr.	Scoville suggested, th			25X1A
25X1A		to advise him of this	and to ask that he		
	presumably to S	SAC and/or	at	advising them	25X1A
		. In particular,	shoule	d be advised of	25X1A
		s concurrence.			

JAMES A. CUNNINGHAM, JR.
Deputy Assistant Director
(Special Activities)

Distribution:

- 1 AD/OSA
- 2 DAD/OSA
- 3 OD/OSA
- 4 DD/OSA
- 5 SB/OSA
- 6 ADMIN/OSA
- 7 MD/OSA
- 8 RB/OSA

DAD/OSA: JACunningham, Jr./mm

Approved For Release 2003 2002 ICIA-RDP63-00313A000600100054-6

IDEA - 0932 Copy # of 5

1 November 1962

EERORANINIH	FOR THE RECORD	
SUBJECT :	Trip to McCoy AFB,	2
field pros	on 22 October, I visited McCoy AFB, Orlandedures on photo equipment and to determine tape recorder.	
2. 0	m the evening of 22 October, I contacted	
		Communications
and demons	trated the pocker recorder.	
L. A	as it turned out, the pilot was so busy w	dth the primary mission
the result	d not have time to give the recorder a to were satisfactory from the standpoint il utility.	thorough work out; howe of fidelity, size, wei
5. examining	had the following suggestions to	make after carefully
	. The microphone jacks should be either to promote interchangeability.	r both male or both
b micro	s. Storage space in the attache case for ophones, etc., could be improved.	r accessory cords,
accor		
shoul	e. For application to the "I" mission, a modate the recorder microphone wire to tild be made.	an adapter that would the pressure suit

a useful tool for debriefing.

Approved For Release 2003/01/24 PCIA RDP63-0313A000600100054-6

IDEA-0932 Page 2

- 6. On the four missions that were completed on 23 October, the time from touchdown of the aircraft to drivesway of the film was a minute or two over or under one hour.
- 7. It was my impression that every one knew his job and did it efficiently. The only serious shortage involved lack of transportation. The around the clock hours that were being put in combined with the fact that SAC had commandeered all the base taxi service made it awkward to get from the line to the quarters.
- 8. Respooling work found necessary to convert 6000 feet rolls of film to 1500 foot missions were done with one of the "B" cameras, which involved possible scratching and static marks.
- p. Preliminary examination of the results of the two speed shutter tests on SO-130 and 8402 film indicate that SO-130 produces a detectable improvement in resolution. This is horseback opinion of several PI's given before definitive examination and enlargement. They also liked the nigher speed (old) shutter.

25X1A

Development Division

CSA-DD/R

Distribution: 1-DD/OSA 2-C/DD/OSA 3-OD/OSA 4-RB/OSA 5-DD (Chros) DD/OSA/NITtrel